

SHORELINE SURVEYS LTD
 Hydrographic — Geophysical — Topographic

Morford Hall, Morston, Dorchester, Dorset DT2 8BA
 Telephone: +44 1305 848821 or +44 7960 038317
 email:shorelinesurveys.com www.shorelinesurveys.com

TITLE:
 Bathymetric Survey of Bude Harbour, Cornwall
 Presenting levels relative to Normal Summer Dock Level

CLIENT:
 Cornwall County Council

PRODUCT:
 Harbour Survey

Project No: J1981 Scale: Date: Surveyed by: TCS
 Drawing No: 02 1:500 05/10/21 Drawn by: TO
 Checked by: EFLP

NOTES/REVISIONS:
 Positions are given in UTM and are based on the datum of the Ordnance Survey datum. Zone data is given where available. Zone data is given where available. Zone data is given where available.

NOTES
 Conducted in 03M15.
 Depth on below Normal Summer Dock Level (NSDL).
 Water level was at NSDL (6.82 metres above ODN) during the survey, equating to 2.2 metres above high/ 8.82 metres above Chart Datum.
 RIR 0025 total and 100 data post-processed using Pinnacle MMS.
 Contours at 0.20 metre intervals.
 Contour interval is not 100%.
 Survey coverage is not 100%.
 Surface-mounted obstructions are not explicitly detected.

